


LEGEND

[Light Blue Box]	YEAR 1 RECLAMATION WORK
[Light Green Box]	YEAR 2 RECLAMATION WORK
[Light Yellow Box]	YEAR 3 RECLAMATION WORK
[Light Orange Box]	YEAR 4 RECLAMATION WORK
[Light Red Box]	YEAR 5 RECLAMATION WORK
[Light Purple Box]	YEAR 6-10 RECLAMATION WORK
[Light Blue Box]	YEAR 11-15 RECLAMATION WORK
[Light Green Box]	YEAR 16-19 RECLAMATION WORK
[Light Yellow Box]	CENTRAL/INFILTRATION DRAIN

- NOTE:**
1. PLANT, CRUSHER, ACCESS ROADS, PIT LIMITS, AND WASTE ROCK STORAGE AREA DESIGNED BY OTHERS.
 2. PLANT SITE SHOWN FOR CLARITY ONLY.
 3. REVEGETATION AREAS ARE APPROXIMATE.
 4. CONTOURS SHOWN FOR EXISTING GROUND, DRY TAILING STACKS AND PIT ARE IN 50' INTERVALS; CONTOURS SHOWN FOR THE WASTE ROCK LEACH PAD ARE IN 20' INTERVALS.
 5. EXISTING ROADS THAT MAY BE RELOCATED, ELIMATED OR HAVE OPERATIONS CANCELED ARE PROVIDED ON ISSUE 5-7 IN THE MAIN PLAN OF OPERATIONS.



Title: RECLAMATION AND CLOSURE PLAN
**ROSEMONT RIDGE
 COMPOSITE OF YEARLY
 RECLAMATION AREAS**

Project: ROSEMONT COPPER
Project no.: 320614
Location: PIMA COUNTY, ARIZONA

Figure no.: 5
Date: 04/08

